

© This drawing and its contents are the property of SLR Consulting Ireland and may not be reproduced or amended by other persons without prior written permission. SLR Consulting Ireland accepts no liability for amendments made by other persons.



Ordnance Survey Ireland Licence no. CYAL50248253
Ordnance Survey Ireland/Government of Ireland
Groundwater data ©GSI
Base Mapping OSi Discovery Series Sheets: 34, 35

LEGEND

- APPLICATION BOUNDARY
- ____ LANDHOLDING BOUNDARY

BEDROCK AQUIFER CLASSIFICATION

PI - Poor Aquifer -

Bedrock which is Generally Unproductive except for Local Zones

----- Bedrock Aquifer Faults



SLR CONSULTING 7 DUNDRUM BUSINESS PARK WINDY ARBOUR D14 N2Y7 T +353 (0)1296 4667 www.slrconsulting.com

P&S CIVIL WORKS LTD ENVIRONMENTAL IMPACT ASSESSMENT

QUARRY AT MULLYMAGOWAN, STRADONE, CO. CAVAN

BEDROCK AQUIFER MAP

FIGURE 7-4

Scale 1:25,000 @ A3

Date **FEBRUARY** 2023