

TIPPERSTOWN
Baile an Tipéaraigh

Silver Pines



Ashgrove House
 Kill Avenue
 Dun Laoghaire
 Co Dublin
 Tel. 01-2804839
 Mob. 086-3819011
 e-mail - thetreefile@eircom.net

Graphic Representation of Tree Form, balance and Protection Zone

Canopy Extent
 Cardinal Radii
 Category Code
 Stem Circumference

Root Protection Area (RPA)
 This area relates to the "RPA" radius as defined in the Tree Survey Table and is measured from the tree centre. This area defines the preliminary Construction Exclusion Zone (CEZ) that must be protected by fencing from the potentially damaging affects of construction activity.

Tree Quality (Categorisation)

- Category "A" Trees (Green Button) Excellent Trees
- Category "B" Trees (Blue Button) Good Trees
- Category "C" Trees (Gray Button) Mediocre to Poor Trees
- Category "U" Trees (Red Button) Dead, Dying or Otherwise Compromised Trees that are Unsustainable.

- Tree Line
- Hedges
- Shrubbery

This Drawing Must Be Read in Conjunction with the Associated Arboricultural Report

Client: Homeland Silverpines Limited
 Scale: 1:500 @ A1 Date: September 2021
 Project: Strategic Housing Development at St Joseph's House and Adjoining Properties

Drawing Title: Tree Constraints Plan