

**Appendix 13.8 PHOTOGRAPHS FROM WALKOVER SURVEY OF PROPOSED WINDFARM DEVELOPMENT –2017- 2023**

View of area in the S of Derryaroge bog (2023).



View of area overgrown in townland of Cloonfore in S of Derryaroge bog (2023).





View of area in the east of the townland of Mount Davys (2023).



View of internal railway in the townland of Mountdavis (2023).





View in an area of cutaway bog and partly overgrown in the SE of Derryaroge bog (2023).



View of railway line that exits Derryaroge Bog in the NE (2023).





View of area rewetted in the east of Derryaroge Bog, taken from the N (2023).



View of area of bog prior to rewetting in 2017, taken from the SE.





View of area overgrown with trees in the north of Derryaroge bog (2023).



View of the north west of Derryaroge bog (2023).





View of ditch excavated in the NE of Mount Davys townland (2017).



General view of the SE of Derryaroge bog (2023).





View of area to the E of Mountdillon Office Works (2023).



View of area adjacent to Mount Dillon site offices (2023).





View of Derryadd bog taken from the N (2023).



General view of overgrown in the NE of Derryadd bog.





General view of overgrown area in middle of Derryadd bog.



View of location of Derradd Bog in the E.





View of area of Recorded Monument LF018-080 in May 2017 and in April 2018.





View of Derryadd Bog in the West.



View of the middle of Derryad bog, from the S.





View of cutaway bog and peat depths along N-S running internal access road in Derryad bog.



View of the 'disused railway field' that runs south in the townland Of Derraghan More, taken from the north (2017).



### Lough Bannow bog



View of higher peat levels at entrance to Lough Bannow Bog and internal haul route from the NW.



View of Lough Bannow Bog north of Derryglogher House





View of west boundary in lough Bannow Bog.



View of peatland in the southeast of the townland of Derrynaskea.





View of area overgrown in the townland of Derrynaskea (2017)



View of areas overgrown in the middle of Lough Bannow Bog (2023).





General view of cutaway bog and area overgrown with vegetation, the middle of Lough Bannow Bog (2023)



General view of area overgrown with vegetation in the east of Lough Bannow Bog (2023).