

CLONASLEE FLOOD RELIEF SCHEME

Appendix 9.3: Photographs

MDW0867
S5 P01
19 May 2025

APPENDIX 9.3: PHOTOGRAPHS



Apx Figure 1: Photographs of a representative reach within the River Clodiagh, where macroinvertebrate, habitat and fish/crayfish habitat appraisal surveys were undertaken in 2021 and 2023. The left photograph shows the reach looking downstream, the central photograph shows the reach looking upstream the right photograph shows substrate within the reach. Photographs were taken on the 28th August 2023.



Apx Figure 2: Photographs of the proposed debris trap location in high flow. From left to right: upstream view, downstream view, right bank, left bank. Photographs taken on 12th March 2024.



Apx Figure 3: Photographs of the proposed debris trap location in low flow. From left to right: upstream view, downstream view, right bank, left bank. Photographs taken on 6th June 2024.



Apx Figure 4: Photographs of Brittas Stream showing from left to right the culvert outlet within the Proposed Scheme area, the stream habitat at the culvert inlet, the stream habitat c. 10m upstream of the culvert inlet and the stream upstream of the Proposed Scheme area. Photographs taken on 12th March 2024.



Apx Figure 5: Photographs of Brittas Stream and River Clodiagh showing from left to right the bridge over the River Clodiagh to the Integrated Constructed Wetland (ICW), the right bank of the River Clodiagh at the ICW, the informal flood wall on the left bank of the River Clodiagh in Area 2, Brittas Stream culvert with no flow. Photographs taken on 6th June 2024.



Apx Figure 6: Photographs of Proposed Scheme area showing from left to right tree no. 16 at the proposed debris trap, Japanese knotweed/hybrid knotweed in Area 2 and new Japanese knotweed/hybrid knotweed growth downstream of Area 2. Photographs taken on 6th June 2024.



Apx Figure 7: Photographs of Proposed Scheme area showing from left to right the bridge over the River Clodiagh to the ICW (looking west) and woodland habitat on the southern side of this access road (Area 3). Photographs taken on 6th June 2024.



Apx Figure 8: Site compound in Area 2, showing hedgerow habitat (H9) along the left bank (looking downstream) of the River Clodiagh. Photograph taken on 6th June 2024.



Apx Figure 9: Agricultural grassland, hedgerow habitat (right) and (mixed) broadleaved woodland (left) in Area 3. Photograph taken on the 6th June 2023.



Apx Figure 10: Photographs of Proposed Scheme area showing from left to right gravel path into Brittas wood (Area 1), location of Brittas Stream culvert under the gravel path (Area 1), path down to River Clodiagh near the proposed debris trap (Area 1) and eroding bank on the River Clodiagh just upstream of Area 3. Photographs taken on 6th June 2024.