



South Quarry new excavation in nase of south quarry floor, October 31st 2015.



South Quarry new excavation of quarry floor in centre right of photograph 31st October 2015



New excavation pits in South Quarry 29th November 2015.



New excavation in South Quarry of quarry floor progressing 29th November 2015.



New excavation in South Quarry of quarry floor progressing 29th November 2015.



Preparation for further blasting in South Quarry 18th December 2015.



Preparation for further blasting in South Quarry 18th December 2015.



Preparation for further blasting in South Quarry 19th December 2015.



Preparation for further blasting in South Quarry 19th December 2015.



Preparation for further blasting in South Quarry 19th December 2015 - Blast took place in early January 2016.



Looking east from west face of quarry – L7265 on right hand side of photograph - September 2012.



Looking west from entrance to quarry - L7265 on left hand side of photograph- September 2012.



Looking North West from local road L7265- September 2012.



Quarry excavation to west of quarry 2 – looking north- September 2012.



2010 Google Earth Map showing stockpile of waste material to east of access road through south quarry.



Google Earth photograph (2010) of stockpile of waste material to the rear of quarry storage shed.



View of stockpile of waste material taken from L7265 - March 2012.



View of stockpile of waste material taken from non-public road - March 2012.



View of waste stockpile taken from lands to south east - March 2012.



View of stockpile of waste material taken from lands to east - March 2012.



Same view as photograph above showing stockpile removed – January 2015.



Photograph from 07th January 2015 showing evidence of waste material dumped over face of quarry.

